

SLIDE-OUTS

Fig. 1 - Venture & Toula Actuator





Fig. 2 - Tuson Actuator



NOTE: Toula actuators and motors can be replaced by Venture.


Part #	Description
125802	Tuson 18:1
132682	Venture 18:1
136373	Venture 28:1

Fig. 3 - Tuson




Embossed
"LCI" Logo
on Bottom
of Gearbox

Fig. 4 - Tuson



Single Motor
Mounting Bolt

Fig. 5 - Venture & Toula



Double
Motor
Mount Bolt

Part #	Actuator & Motor (18:1)	Size
119128	Venture	24"
122747	Venture	32"
119129	Venture	40"
145595	Venture Actuator Only	40"
145185	Tuson	24"
131903	Tuson	40"
145596	Tuson Actuator Only	40"

As a supplier of components to the RV industry, safety, education and customer satisfaction are our primary concerns. Should you have any questions, please do not hesitate to contact us at (574) 537-8900 or by email at customerservice@lci1.com. Self-help tips, technical documents, product videos and a training class schedule are available at www.lci1.com or by downloading the MyLCI app.